


# Program Card Manual



-ESC -Connect with ESC-set

-External power -Connect external power(4-6V). You should connect the ECS with external power of 4-6V if the ESC without BEC.

-Brake on -brake is active

-Brake off -non active brake

-Normal Motors -for2,4,6pole motors.This timing gives maximum efficiency.

-Out rnners -strongly recommended for outrunners

-Cut off type hard -motor is fully off immediately after reaching cut off voltage

-Cut off type slow down -motor turns off slowly by power reduction

-Throttle curve linear -half throttle is equal as 60% of maximum RPM

-Throttle curve logarithm -half throttle is equal as 80% of maximum RPM

Default Voltage:Cut off is set to 0,9V per cell for NiXX,3,0Vper cell for Li-XX